## **Manhole Inspection Report**



Date:

05/11/2018

Weather:

Cert. #:

Coding:

**RZMACP** 

MH#:

M-1004-008

Owner: NA Len. Surveyed: 8.3

P.O.#:

Surveyor: Jen Costello Rim to Invert: Wall Material:

Concrete (reinforced)

8.7

Street:

**Intersection of Coral Dr. and McAfee** Project:

Hobart, IN

City:

Customer:

Hobart, IN

**GPS Northing:** 2914652.489

Location:

GPS Easting:

U-907-5518

2914652.489

Drain Area:

**Sub-Meter** 

Cover Shape:

Northeast Circular

GPS Accuracy: Evidence of Surcharge:

0000

No

Cover Size:

22.5

Potential for Runoff:

None

Comments:

O&M Index:

0.00 O&M Quick:

0000 O&M Rating: 0000 Structural Rating: 0.00 0.00

0.00

Structural Index: Overall Index:


0.00 Structural Quick: 0.00 Overall Quick:

Overall Rating:

Wednesday, May 3, 2023

1

	Position	Code	Observation	Video (sec)	Grade
M-1004-008					
$\sim$	0	MGO	General Observation	10	NA
- 11	2.7	MGO	General Observation	29	NA
- 11	8.3	MGO	General Observation	54	NA
Camera Direction					



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 2.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 8.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3