## **Manhole Inspection Report**



Date:

Customer:

05/08/2018

Weather:

Coding: RZMACP

MH#:

M-1004-034

Owner: NA

Len. Surveyed: Rim to Invert:

P.O.#:

Surveyor: Cert. #: Jen Costello U-907-5518

Wall Material:

Concrete (reinforced)

9.1

10.1

Street: City: **Intersection of Hillcrest Ave. and Dr** Project:

GPS Northing:

Hobart, IN 2912757.863

Location:

CDC F ...

2012707.000

Drain Area:

GPS Easting:

2912757.863

Cover Shape:

Northeast

Hobart, IN

GPS Accuracy: Sub-Meter

Cover Size:

Other 22.5

Evidence of Surcharge: No

0000

Comments:

Potential for Runoff:

noff: None

O&M Index: Structural Index:

Overall Index:

0.00

0.00

.00 O&M Quick:

Structural Quick:
Overall Quick:

0000 O&M Rating: 0000 Structural Rat

Structural Rating:
Overall Rating:

0.00

0.00

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M-1004-034				
0.	MGP	General Photo	10	NA
2.3	MGO	General Observation	29	NA
9.1	MGO	General Observation	56	NA
Camera Direction				


Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 9.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

3