## **Manhole Inspection Report**



Date: 05/11/2018 Weather:

MH#: M-1004-052 Owner: NA Len. Surveyed: 5.4 P.O.#: Surveyor: Jen Costello Rim to Invert: 5.5

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

**RZMACP** 

Coding:

**Intersection of Barberry Dr. and He** Project: Street: City:

Hobart, IN Hobart, IN GPS Northing: 2913914.849

Location: GPS Easting: 2913914.849

Drain Area: Northeast **GPS Accuracy:** Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No Potential for Runoff: Cover Size: 22.5 None

Comments:

	O&M Rating:	0.00
ck: <b>0000</b>	Structural Rating:	0.00
0000	Overall Rating:	0.00
	2000	Structurur Nating.

1 Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade		
M-1004-052							
	V.0	MGP	General Photo	10	NA		
- 11	2.0	MGO	General Observation	28	NA		
- 11	5.4	MGO	General Observation	48	NA		
Camera Direction							

Code:



**General Photo** Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH** 

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 5.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3