## **Manhole Inspection Report**



Date:

05/11/2018

Weather:

Cert. #:

**RZMACP** 

MH#:

M-1004-057

Owner: NA

Len. Surveyed: 8.5

P.O.#:

Surveyor:

Jen Costello U-907-5518

Rim to Invert: Wall Material:

Coding:

Concrete

(reinforced)

Street:

Customer:

**Intersection of Laurel Ct. and Barber** Project:

Hobart, IN

City:

**GPS Northing:** 

2913206.028

Location:

GPS Easting:

2913206.028

Drain Area:

GPS Accuracy:

**Sub-Meter** 

Cover Shape: Cover Size:

Northeast Circular

22.5

Hobart, IN

Evidence of Surcharge: No

Potential for Runoff: None

Comments:

2.00 O&M Quick:

2.00

2100 0000

2100

O&M Rating:

2.00 0.00

2.00

O&M Index: Structural Index: Overall Index:

0.00 Structural Quick:

Overall Quick:

Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

Posi	tion Code	Observation	Video (sec)	Grade
M-1004-057				
.0	MGP	General Photo	10	NA
1.5	MGO	General Observation	26	NA
7.6	IW	Infil Weeper	52	M 2
8.5	MGO	General Observation	65	NA
Camera Direction				

Code:



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:	ACCESS MH		

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 7.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 1

Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 8.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023