## **Manhole Inspection Report**



Date:

05/11/2018

Weather:

Coding:

**RZMACP** 

MH#:

M-1004-074

Owner: NA Len. Surveyed: 3.9

P.O.#:

Surveyor: Cert. #:

Overall Quick:

Jen Costello U-907-5518

Rim to Invert: Wall Material:

Concrete (reinforced)

4.5

Street: City:

Customer:

Tulip Ln. 378' West of Hemlock Dr.

Project:

Hobart, IN 2913502.001

Location:

Hobart, IN

**GPS Northing:** GPS Easting:

Drain Area:

Northeast

2913502.001

Cover Shape:

Circular

GPS Accuracy: **Sub-Meter** Evidence of Surcharge:

No

Cover Size:

22.5

Potential for Runoff: None

Comments:

O&M Index: Structural Index:

Overall Index:

0.00	O&M Quick:	
0.00	Structural Quick:	

0.00


0000 O&M Rating: 0000 Structural Rating: 0000 Overall Rating:

0.00 0.00 0.00

Wednesday, May 3, 2023

1

Positi	on Code	Observation	Video (sec)	Grade
M-1004-074				
.0	MGO	General Observation	10	NA
1.0	MGO	General Observation	25	NA
3.9	MGO	General Observation	44	NA
Camera Direction				



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 1.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 3.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3