Manhole Inspection Report



Date:

05/11/2018

Weather:

Coding: RZMACP

6.5

6.8

MH#:

Customer:

M-1004-091

Owner: NA

Len. Surveyed: Rim to Invert:

P.O.#:

Surveyor: Cert. #: Jen Costello U-907-5518

Wall Material:

Concrete (reinforced)

Street: City: Cypress Ln. 590' East of Poplar Ln.

Project: Hobart, IN

Location:

Hobart, IN

GPS Northing:

2913142.599

Drain Area: Northea

GPS Easting:

2913142.599

Cover Shape:

Northeast Circular GPS Accuracy: Sub-Meter Evidence of Surcharge: No

Cover Size:

22.5

Potential for Runoff: None

0000

Comments:

O&M Index: Structural Index:

Overall Index:

0.00

0.00

_O&M Quick:
_Structural Quick:
Overall Quick:

0000 O&M Rating:
0000 Structural Rating:

Overall Rating:

0.00 0.00 0.00

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M-1004-091				
.0	MGO	General Observation	10	NA
1.5	MGO	General Observation	26	NA
6.5	MGO	General Observation	49	NA
Camera Direction				

Code:



Description: **General Observation** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: access mh

MGO

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: MGO

Description: General Observation

Distance (ft): 6.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey