## **Manhole Inspection Report**



Date: 05/11/2018 Weather: Coding:

 MH#:
 M-1004-093
 Owner:
 NA
 Len. Surveyed:
 7.4

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 7.9

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

**RZMACP** 

Street: Cypress Ln. 315' East of Poplar Ln. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2912875.17 Location: GPS Easting: 2912875.17

Drain Area: Northeast GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2200 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2200 4.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-1004-093				
.0	MGP	General Photo	10	NA
1.2	MGO	General Observation	26	NA
7.0	IW	Infil Weeper	51	M 2
7.0	DSF	Deposits Settled Fine	63	M 2
7.4	MGO	General Observation	75	NA
Camera Direction				



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	ACCESS MH	

MGP

Wednesday, May 3, 2023

Code:



Code: MGO

Description: General Observation

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 7.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 7.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023





Code: MGO

Description: General Observation

Distance (ft): 7.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY