Manhole Inspection Report



Date: 05/11/2018 Weather: Coding: RZMACP

MH#: M-1004-096 Owner: NA Len. Surveyed: 6.0
P.O.#: Surveyor: Jen Costello Rim to Invert: 6.5

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street:Juniper Ct.Project:Hobart, INCity:Hobart, INGPS Northing:2913471.967

Location: GPS Easting: 2913471.967
Drain Area: Northeast GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-1004-09	6				
	.0	MGP	General Photo	10	NA
- 11	6.0	MGO	General Observation	33	NA
Camera Direction					


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH**

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 6.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY