Manhole Inspection Report



Date: 09/27/2022 Weather: Coding: RZMACP

 MH#:
 M-1005-002
 Owner:
 NA
 Len. Surveyed:
 2.4

 P.O.#:
 Surveyor:
 Todd Machine
 Rim to Invert:
 2.8

Customer: Cert. #: P0038859-082022 Wall Material: Concrete (cast in

place)

Street: 466' North of Hwy 130. 952' East of Project: Hobart, IN

City:Hobart, INGPS Northing:2288066.438Location:Local Rural StreetsGPS Easting:2912658.886Drain Area:SoutheastGPS Accuracy:Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 1.00 1200 2.00 Structural Index: Structural Quick: Structural Rating: 1.33 2112 4.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, November 30, 2022

	Code	Observation	Video (sec)	Grade
5-002				
0.	MGO	General Observation	10	NA
0.	SRI	Surface Roughness Increased	21	S 1
2.4	DSC	Deposits Settled Compacted	37	M 2
2.4	SRI	Surface Roughness Increased	48	S 1
2.4	MGO	General Observation	59	NA

Code:

Description:



·	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	access mh

MGO

General Observation



Code: SRI

Description: Surface Roughness Increased

Distance (ft): .0
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: DSC

Description: Deposits Settled Compacted

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value: 2

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 2.4
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: End Of Survey