Manhole Inspection Report



Date: 04/18/2018 Weather: Coding: RZMACP

MH#: M-103-009 Owner: NA Len. Surveyed: 6.2
P.O.#: Surveyor: Jen Costello Rim to Invert: 8.9

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: Alley between Willow St. and Howa Project: Hobart, IN

City: Hobart, IN GPS Northing: 2890932.469

Location: GPS Easting: 2890932.469

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 1.00 1.00 1100 Structural Index: Structural Quick: Structural Rating: 1.50 2111 3.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
I- 1 03-009				
.0	MGO	General Observation	10	NA
1.3	MGO	General Observation	26	NA
/1.3	SRI	Surface Roughness Increased	39	S 1
4.4	IW	Infil Weeper	57	M 2
6.2	MGO	General Observation	72	NA



Code: MGO
Description: General Observation

ACCESS MH

2

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 1.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 1.3
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: IW

Description: Infil Weeper

Distance (ft): 4.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 4
1st Value: 2
2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 6.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023