Date:	04/18/2018	Weather:		Coding:	RZMACP
MH#:	M-103-112	Owner:	NA	Len. Surveyed:	7.4
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	8.7
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Swift St. 297' Soutl	n of 39th Ave.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2889129.407	
Location:			GPS Easting:	2889129.407	
Drain Area:	Northwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	23.0		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick		Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
м-103-112	2				
\leq	.0	MGP	General Photo	10	NA
	1.2	IS	Infil Stain	24	NA
	/ 2.2	MGP	General Photo	40	NA
	5.5	DAZ	Deposits Attached Other	60	M 2
	6.6	MGO	General Observation	73	NA
Camera Direction					



Code:	MGP
Description:	General Photo
	-
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
Distance (ft):	1.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	2.2 0 0
nemano.	



Code: Description:	DAZ Deposits Attached Other
Distance (ft):	5.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	10.000
Step:	NO
Remarks:	Mixed materials



Code: Description: MGO General Observation

Distance (ft):	6.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.