## **Manhole Inspection Report**



Date:

04/16/2018

Weather:

Coding: **RZMACP** 

MH#:

M-103-131

Owner: NA Len. Surveyed: 10.2

P.O.#:

Customer:

Surveyor: John Kuglmaier U-1215-07002349 Cert. #:

Rim to Invert:

11.6 Concrete Wall Material:

(reinforced)

Street:

38th Ave. 166' West of Swift St.

Project:

City:

Hobart, IN

**GPS Northing:** 

Hobart, IN

Location:

GPS Easting:

0.0 0.0

Drain Area:

Northwest

GPS Accuracy:

**Nearest Meter** 

Cover Shape:

Circular

Evidence of Surcharge:

Cover Size:

23.0

No Potential for Runoff:

None

Comments:

0.00 O&M Quick:

0000 0000

O&M Rating: Structural Rating: 0.00 0.00

0.00

O&M Index: Structural Index: Overall Index:

0.00 Structural Quick: 0.00 Overall Quick:

0000 Overall Rating:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M-(103-1)31				
.0	MGP	General Photo	10	NA
2.0	MGP	General Photo	28	NA
8.1	IS	Infil Stain	54	NA
9.5	MGO	General Observation	68	NA
Camera Direction				

Code:

Description:



Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Step:

NO

Remarks:

MGP

**General Photo** 

Kemai



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 8.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 8

Clock To:

1st Value: 2nd Value: Value Percent:

Step: YES

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 9.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3