Manhole Inspection Report



Date: 03/20/2018 Weather: Coding: RZMACP

 MH#:
 M-108-026
 Owner:
 NA
 Len. Surveyed:
 7.0

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.6

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 568' North of West 15th Pl. West of Project: Hobart, IN

 City:
 Hobart, IN
 GPS Northing:
 2889460.183

 Location:
 GPS Easting:
 2889460.183

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	2.00	Structural Quick:	2100	Structural Rating:	2.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-108-026				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
2.3	SSS	Surface Spalling	43	S 2
5.6	MGO	General Observation	61	NA
Camera Direction				


Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP


Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: SSS

Description: Surface Spalling

Distance (ft): 2.3
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 1
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 5.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.