Date:	04/17/2018	Weather:		Coding:	RZMACP
MH#:	M-203-038	Owner:	NA	Len. Surveyed:	7.3
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	8.6
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Alley between 37th	Ave. and 38th A	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Northwest		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	23.0		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qui	ck: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick	3121	Overall Rating:	5.00

	Position	Code	Observation	Video (sec)	Grade
м-203-03	8				
$\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{$	.0	MGO	General Observation	10	NA
	1.3	MGP	General Photo	25	NA
	/1.3	SAV	Surface Aggregate Visible	38	S 3
	6.5	OBR	Obstacle Rocks	61	M 2
/	7.3	MGO	General Observation	74	NA
Camera Direction					



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

\_\_\_\_



Code: Description:	MGP General Photo
Distance (ft):	1.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code: Description:	SAV Surface Aggregate Visible
Distance (ft):	1.3
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



OBR Obstacle Rocks
6.5
0
2
6
5
5.000
NO



Code:MGODescription:General Observation

Distance (ft):	7.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY