
| Date: | 04/17/2018 | Weather: | | Coding: | RZMACP |
|--------------------------|--------------------|------------------|------------------------|--------------------|--------------------------|
| MH#: | M-203-054 | Owner: | NA | Len. Surveyed: | 6.7 |
| P.O.#: | | Surveyor: | Jen Costello | Rim to Invert: | 8.3 |
| Customer: | | Cert. #: | U-907-5518 | Wall Material: | Concrete (reinforced) |
| Street: | Sandusky St. and E | vergreen St. and | Project: | Hobart, IN | |
| City: | Hobart, IN | | GPS Northing: | 0.0 | |
| Location: | | | GPS Easting: | 0.0 | |
| Drain Area: | Northwest | | GPS Accuracy: | Nearest Meter | |
| Cover Shape: | Circular | | Evidence of Surcharge: | No | |
| Cover Size: Comments: | 23.0 | | Potential for Runoff: | None | |
| O&M Index: | 2.00 | O&M Quick: | 2100 | O&M Rating: | 2.00 |
| Structural Index: | 2.00 | Structural Qu | iick: 2100 | Structural Rating: | 2.00 |
| Overall Index: | 2.00 | Overall Quic | <: 2200 | Overall Rating: | 4.00 |

| N-03-054 1.3 MGP General Observation 10 NA 1.3 MGP General Photo 26 NA 1.3 SSS Surface Spalling 36 S 2 5.3 DSF Deposits Settled Fine 58 M 2 6.7 MGO General Observation 72 NA | Position | Code | Observation | Video (sec) | Grade |
|--|----------|------|-----------------------|-------------|-------|
| .0MGOGeneral Observation10NA1.3MGPGeneral Photo26NA1.3SSSSurface Spalling36S 25.3DSFDeposits Settled Fine58M 26.7MGOGeneral Observation72NA | 203-054 | | | | |
| 1.3SSSSurface Spalling36S 25.3DSFDeposits Settled Fine58M 26.7MGOGeneral Observation72NA | | MGO | General Observation | 10 | NA |
| 5.3 DSF Deposits Settled Fine 58 M 2 6.7 MGO General Observation 72 NA | 1.3 | MGP | General Photo | 26 | NA |
| 6.7 MGO General Observation 72 NA | /1.3 | SSS | Surface Spalling | 36 | S 2 |
| | 5.3 | DSF | Deposits Settled Fine | 58 | M 2 |
| | 6.7 | MGO | General Observation | 72 | NA |
| | | | | | |



| Code: Description: | MGO General Observation |
|-----------------------|----------------------------|
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | NO |
| Remarks: | access MH |



| Code: Description: | MGP General Photo |
|-----------------------|----------------------|
| | |
| Distance (ft): | 1.3 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | NO |
| Remarks: | UNDERSIDE OF FRAME |



| Code: Description: | SSS Surface Spalling |
|-----------------------|-------------------------|
| | |
| Distance (ft): | 1.3 |
| Structural Grade: | 2 |
| O&M Grade: | 0 |
| Clock Start/From: | 12 |
| Clock To: | 12 |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | NO |
| Remarks: | |
| | |



| Code: | DSF |
|-------------------|------------------------------|
| Description: | Deposits Settled Fine |
| | |
| Distance (ft): | 5.3 |
| . , | - |
| Structural Grade: | 0 |
| O&M Grade: | 2 |
| Clock Start/From: | 12 |
| Clock To: | 12 |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 10.000 |
| Step: | NO |
| Remarks: | |



Code:MGODescription:General Observation

| Distance (ft): | 6.7 |
|-------------------|------------|
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | NO |
| Remarks: | END SURVEY |