| Date:                    | 04/17/2018          | Weather:        |                       | Coding:            | RZMACP                   |
|--------------------------|---------------------|-----------------|-----------------------|--------------------|--------------------------|
| MH#:                     | M-203-063           | Owner:          | NA                    | Len. Surveyed:     | 5.6                      |
| P.O.#:                   |                     | Surveyor:       | Jen Costello          | Rim to Invert:     | 7.7                      |
| Customer:                |                     | Cert. #:        | U-907-5518            | Wall Material:     | Concrete<br>(reinforced) |
| Street:                  | Alley between 38th  | Ave. and 39th A | Project:              | Hobart, IN         |                          |
| City:                    | Hobart, IN          | C               | GPS Northing:         | 0.0                |                          |
| Location:                |                     | C               | GPS Easting:          | 0.0                |                          |
| Drain Area:              | ain Area: Northwest |                 | GPS Accuracy:         | Nearest Meter      |                          |
| Cover Shape:             | Circular            | E               | vidence of Surcharge: | No                 |                          |
| Cover Size:<br>Comments: | 23.0                | F               | Potential for Runoff: | None               |                          |
| O&M Index:               | 2.00                | O&M Quick:      | 2100                  | O&M Rating:        | 2.00                     |
| Structural Index:        | 0.00                | Structural Quic | k: 0000               | Structural Rating: | 0.00                     |
| Overall Index:           | 2.00                | Overall Quick:  | 2100                  | Overall Rating:    | 2.00                     |

| Position         | Code | Observation           | Video (sec) | Grade |
|------------------|------|-----------------------|-------------|-------|
| M-203-063        |      |                       |             |       |
| .0               | MGO  | General Observation   | 10          | NA    |
| .7               | IS   | Infil Stain           | 23          | NA    |
| 1.4              | MGO  | General Observation   | 37          | NA    |
| 2.6              | IS   | Infil Stain           | 53          | NA    |
| / 5.4            | DSF  | Deposits Settled Fine | 70          | M 2   |
| 5.6              | MGO  | General Observation   | 82          | NA    |
| Camera Direction |      |                       |             |       |




| Code:<br>Description: | MGO<br>General Observation |
|-----------------------|----------------------------|
| Distance (ft):        | .0                         |
| Structural Grade:     | 0                          |
| O&M Grade:            | 0                          |
| Clock Start/From:     |                            |
| Clock To:             |                            |
| 1st Value:            |                            |
| 2nd Value:            |                            |
| Value Percent:        |                            |
| Step:                 | NO                         |
| Remarks:              | ACCESS MH                  |



| Code:             | IS          |
|-------------------|-------------|
| Description:      | Infil Stain |
|                   |             |
| // )              | _           |
| Distance (ft):    | .7          |
| Structural Grade: | 0           |
| O&M Grade:        | 0           |
| Clock Start/From: | 3           |
| Clock To:         |             |
| 1st Value:        |             |
| 2nd Value:        |             |
| Value Percent:    |             |
| Step:             | NO          |
| Remarks:          |             |



| Code:   | MGO                 |
|---|---------------------|
| Description:  | General Observation |
| Distance (ft):<br>Structural Grade:<br>O&M Grade:<br>Clock Start/From:<br>Clock To:<br>1st Value:<br>2nd Value:<br>Value Percent: | 1.4<br>0<br>0       |
| Step:   | NO                  |
| Remarks:  | UNDERSIDE OF FRAME  |



| Code:<br>Description: | IS<br>Infil Stain |
|-----------------------|-------------------|
| Distance (ft):        | 2.6               |
| Structural Grade:     | 0                 |
| O&M Grade:            | 0                 |
| Clock Start/From:     | 8                 |
| Clock To:             |                   |
| 1st Value:            |                   |
| 2nd Value:            |                   |
| Value Percent:        |                   |
| Step:                 | NO                |
| Remarks:              |                   |



Code:DSFDescription:Deposits Settled Fine

| Distance (ft):    | 5.4   |
|-------------------|-------|
| Structural Grade: | 0     |
| O&M Grade:        | 2     |
| Clock Start/From: | 9     |
| Clock To:         | 3     |
| 1st Value:        |       |
| 2nd Value:        |       |
| Value Percent:    | 5.000 |
| Step:             | NO    |
| Remarks:          |       |



| Code:  | MGO                 |
|--|---------------------|
| Description:   | General Observation |
|  |                     |
| Distance (ft):   | 5.6                 |
| Structural Grade:  | 0                   |
| O&M Grade:   | 0                   |
| Clock Start/From:  |                     |
| Clock To:  |                     |
| 1st Value:   |                     |
| 2nd Value:   |                     |
| Value Percent:   |                     |
| Step:  | NO                  |
| Remarks:   | END SURVEY          |
| Clock To:<br>1st Value:<br>2nd Value:<br>Value Percent:<br>Step: |                     |