Manhole Inspection Report



Date: 03/23/2018 Weather: Coding: RZMACP

 MH#:
 M-208-002
 Owner:
 NA
 Len. Surveyed:
 8.7

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 9.5

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 304' East of Minnesota St. East of 59 Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

| O&M Index: | 2.00 | O&M Quick: | 2100 | O&M Rating: | 2.00 |
|-------------------|------|-------------------|------|--------------------|------|
| Structural Index: | 0.00 | Structural Quick: | 0000 | Structural Rating: | 0.00 |
| Overall Index: | 2.00 | Overall Quick: | 2100 | Overall Rating: | 2.00 |

Wednesday, May 3, 2023

| Position | Code | Observation | Video (sec) | Grade |
|----------|------|-------------------------|-------------|-------|
| 08-002 | | | | |
| .0 | MGP | General Photo | 10 | NA |
| 2.2 | MGP | General Photo | 28 | NA |
| 3.7 | IS | Infil Stain | 45 | NA |
| 4.7 | IS | Infil Stain | 58 | NA |
| 5.4 | DAZ | Deposits Attached Other | 71 | M 2 |
| 7.2 | MGO | General Observation | 86 | NA |
| | | | | |



| Description: | General Photo | | |
|-------------------|---------------|--|--|
| | | | |
| Distance (ft): | .0 | | |
| Structural Grade: | 0 | | |
| O&M Grade: | 0 | | |
| Clock Start/From: | | | |
| Clock To: | | | |
| 1st Value: | | | |
| 2nd Value: | | | |
| Value Percent: | | | |
| Step: | NO | | |
| Remarks: | | | |

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 3.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10
Clock To: 2
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: IS

Description: Infil Stain

Distance (ft): 4.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 4
Clock To: 9
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 5.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 7.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.