Date:	03/26/2018	Weather:		Coding:	RZMACP
MH#:	M-208-013	Owner:	NA	Len. Surveyed:	13.2
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	14.3
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Intersection of Brookview Ct. and 58 Project: Hoba			Hobart, IN	
City:	Hobart, IN	G	GPS Northing:	0.0	
Location:		G	GPS Easting:	0.0	
Drain Area:	Southwest	(SPS Accuracy:	Nearest Meter	
Cover Shape:	Circular	E	vidence of Surcharge:	Yes	
Cover Size: Comments:	22.5	F	Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quic	k: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00


Position	Code	Observation	Video (sec)	Grade
1-208-013				
0.	MGP	General Photo	10	NA
2.4	MGP	General Photo	29	NA
/4.6	IS	Infil Stain	47	NA
/ 10.2	DAZ	Deposits Attached Other	69	M 2
12.0	MGO	General Observation	84	NA



Code:	MGP
Description:	General Photo
	2
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft):	2.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	IS Infil Stain
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value:	4.6 0 12 12
Value Percent: Step: Remarks:	NO



Code: Description:	DAZ Deposits Attached Other
Distance (ft):	10.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	10.000
Step:	NO
Remarks:	Mixed materials



Code: Description: MGO General Observation

Distance (ft):	12.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.