## **Manhole Inspection Report**



Date:

Customer:

03/26/2018

Weather:

Coding:

**RZMACP** 

13.4

13.6

MH#:

M-208-014

Owner: NA Len. Surveyed:

P.O.#:

Surveyor: Cert. #:

John Kuglmaier U-1215-07002349 Rim to Invert: Wall Material:

Concrete (reinforced)

Street:

58th Pl. 408' East of Liverpool Rd.

City:

Hobart, IN

**GPS Northing:** 

Hobart, IN 0.0

Location: Drain Area: GPS Easting:

Project:

0.0

Cover Shape:

Southwest

GPS Accuracy:

**Nearest Meter** 

Cover Size:

Circular

22.5

Evidence of Surcharge: Potential for Runoff:

Yes None

Comments:

O&M Index:

2.00 O&M Quick:

0.00

2100 0000

2100

2.00 O&M Rating: 0.00

2.00

Structural Index: Overall Index:

Structural Quick: 2.00 Overall Quick:

Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

	Code	Observation	Video (sec)	Grade
208-014				
.0	MGP	General Photo	10	NA
2.6	MGP	General Photo	29	NA
/4.3	IS	Infil Stain	46	NA
8.2	DSF	Deposits Settled Fine	65	M 2
/ / 11.3	MGO	General Observation	83	NA



Description:	<b>General Photo</b>
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 4.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 5
Clock To: 7
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Code:



DSF

Description: Deposits Settled Fine

Distance (ft): 8.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 11.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023