## **Manhole Inspection Report**



Date: 03/22/2018 Weather: Coding: RZMACP

MH#: M-208-024 Owner: NA Len. Surveyed: 7.2
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 8.2

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: North of 61st Ave. 204' East of Liver Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes


Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
<b>Л-208-024</b>				
.0	MGP	General Photo	10	NA
2.4	MGP	General Photo	29	NA
3.8	DSF	Deposits Settled Fine	45	M 2
5.7	MGO	General Observation	60	NA
Camera Direction				



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 3.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 5.7
Structural Grade: 0

O&M Grade: **0** 

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: Step: **NO** 

Remarks: Ins. Comp.

Wednesday, May 3, 2023