## **Manhole Inspection Report**



Date:

03/23/2018

Weather:

Cert. #:

Coding:

**RZMACP** 

6.6

6.9

MH#:

M-208-027

Owner: NA Len. Surveyed:

P.O.#:

Surveyor:

John Kuglmaier Rim to Invert:

> Concrete Wall Material: (reinforced)

Street:

Customer:

North of 61st Ave. 283' East of Minn Project:

Hobart, IN 0.0

City: Location: Hobart, IN

**GPS Northing:** 

U-1215-07002349

GPS Easting: 0.0

Drain Area:

Southwest

GPS Accuracy:

**Nearest Meter** 

Cover Shape:

Circular

Evidence of Surcharge: No

Cover Size:

22.5

Potential for Runoff:

None

Comments:

O&M Index: Structural Index:

Overall Index:

0.00

0.00 O&M Quick: 0.00 Structural Quick:

Overall Quick:

0000 O&M Rating: 0000 Structural Rating: 0000 Overall Rating:

0.00 0.00 0.00

Wednesday, May 3, 2023

1

$\sim$	osition Code	Observation	Video (sec)	Grade
M-208-027				
.0	MGP	General Photo	10	NA
2.0	D IS	Infil Stain	26	NA
2.4	4 MGP	General Photo	41	NA
2.	7 IS	Infil Stain	55	NA
5.3	3 MGC	General Observation	72	NA
Camera Direction				



Description:	<b>General Photo</b>
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2

Code:



Code: IS

Description: Infil Stain

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Step: NO

Remarks:




Code: IS

Description: Infil Stain

Distance (ft): 2.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 5
Clock To: 8
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 5.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023