Date:	03/25/2018	Weather:		Coding:	RZMACP
MH#:	M-209-012	Owner:	NA	Len. Surveyed:	7.1
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	7.7
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	North of 62nd Pl. 1	54' East of Califor	Project:	Hobart, IN	
City:	Hobart, IN	(GPS Northing:	0.0	
Location:		(GPS Easting:	0.0	
Drain Area:	Southwest	(GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular	I	Evidence of Surcharge:	Yes	
Cover Size: Comments:	22.5	I	Potential for Runoff:	None	
O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
				Structural Rating:	3.00
O&M Index: Structural Index: Overall Index:	3.00 0.00 3.00	O&M Quick: Structural Quic Overall Quick:	ck: 0000		Rating:

P	osition	Code	Observation	Video (sec)	Grade
-209-012					
.0	l	MGP	General Photo	10	NA
1.	9	IS	Infil Stain	26	NA
	7	MGP	General Photo	41	NA
3.	9	DAZ	Deposits Attached Other	57	M 3
5.	7	MGO	General Observation	72	NA



Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
Distance (ft):	1.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	2.7 0 0
Step: Remarks:	ΝΟ



Code:	DAZ
Description:	Deposits Attached Other
	• •
Distance (ft):	3.9
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	15.000
Step:	NO
Remarks:	Mixed materials



Code:MGODescription:General Observation

Distance (ft):5.7Structural Grade:0O&M Grade:0Clock Start/From:Clock To:Start/From:-1st Value:-2nd Value:-Value Percent:-Step:NORemarks:Ins. Comp.