Manhole Inspection Report



Date: 03/22/2018 Weather:

M-209-014 MH#: Owner: NA Len. Surveyed: 11.3 P.O.#: Rim to Invert: 11.6 Surveyor: John Kuglmaier U-1215-07002349 Concrete Customer: Cert. #: Wall Material:

Project:

(reinforced)

RZMACP

Coding:

Hobart, IN

Nearest Meter

Street: **61st Pl. Between California St. and**

Southwest

Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: Potential for Runoff: None

Comments:

Drain Area:

City:

3.00 3100 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 3.00 3100 3.00 Overall Index: Overall Quick: Overall Rating:

GPS Accuracy:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-209-014				
.0	MGP	General Photo	10	NA
2.2	MGP	General Photo	28	NA
7.4	DSF	Deposits Settled Fine	52	M 3
10.0	MGO	General Observation	68	NA
Camera Direction				




Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023

Code:



MGP Code:

Description: **General Photo**

Distance (ft): 2.2 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: **Deposits Settled Fine**


Distance (ft): 7.4 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 12 Clock To: 12 1st Value:

2nd Value:

Value Percent: 15.000 NO

Remarks:

Step:





Distance (ft): 10.0 Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3