## **Manhole Inspection Report**



Date: 03/24/2018 Weather:

Coding:

**RZMACP** 

MH#:

M-209-023

Owner: NA Len. Surveyed:

P.O.#:

John Kuglmaier Surveyor:

Rim to Invert:

12.0 Concrete

11.8

Customer:

Cert. #:

U-1215-07002349

Wall Material:

(reinforced)

Street:

East of Liverpool Rd. 275' South of 6 Project:

Hobart, IN

City:

**GPS Northing:** 

0.0

Location: Drain Area:

GPS Easting: 0.0

Cover Shape:

Southwest

GPS Accuracy:

**Nearest Meter** 

Circular

Hobart, IN

Evidence of Surcharge: No

Cover Size:

22.5

Potential for Runoff: None

Comments:

O&M Index:

2.00 3.00

O&M Quick: Structural Quick:

2100 3800

3821

O&M Rating:

2.00 24.00

26.00

Structural Index: Overall Index:

2.89 Overall Quick: Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
209-023				
.0	MGP	General Photo	10	NA
1.3	SAV	Surface Aggregate Visible	24	S 3
2.4	MGP	General Photo	40	NA
8.4	DAZ	Deposits Attached Other	66	M 2
9.8	MGO	General Observation	80	NA
9.8	SAV	Surface Aggregate Visible	91	S 3

Code:



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 1.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 8.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value:

Value Percent: 10.000
Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 9.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 9.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 4