Manhole Inspection Report



Date:

03/22/2018

Weather:

NA

Coding:

RZMACP

MH#: P.O.#:

M-209-024

Owner:

Rim to Invert:

Len. Surveyed: 10.8 12.6

Customer:

Surveyor: Cert. #:

John Kuglmaier U-1215-07002349

Wall Material:

Concrete (reinforced)

Street:

61st Pl. 173' East of Liverpool Rd.

Project:

Hobart, IN

City:

Hobart, IN

GPS Northing:

0.0

Yes

None

Location:

GPS Easting: 0.0

Drain Area:

Southwest

GPS Accuracy:

Nearest Meter

Cover Shape: Cover Size:

Circular 22.5

Evidence of Surcharge: Potential for Runoff:

Comments:

2.00 O&M Quick: 0.00

O&M Rating: Structural Rating:

2.00 0.00 2.00

O&M Index: Structural Index: Overall Index:

Structural Quick: 2.00 Overall Quick:

2100 Overall Rating:

2100

0000

Wednesday, May 3, 2023

1

		10 27 54 67	NA NA M 2 NA
MGP General DSF Deposits	Photo Settled Fine	27 54	NA M 2
OSF Deposits	Settled Fine	54	M 2
MGO General	Observation	67	NA

Code:



Description:	General Photo
Distance (ft): Structural Grade: O&M Grade:	.0 0 0
Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	
Step: Remarks:	NO

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 1.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 8.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value: Value Percent:

10.000 NO

Step:

Remarks:

Code:

MGO

Description: General Observation



Distance (ft): 9.4

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3