Manhole Inspection Report



Date:

03/22/2018

Weather:

Surveyor:

NA

Coding:

RZMACP

MH#: P.O.#:

M-209-025

Owner:

John Kuglmaier

Rim to Invert:

Len. Surveyed: 12.9 13.4

Customer:

Cert. #:

U-1215-07002349

Wall Material:

Concrete (reinforced)

Street: City:

Intersection of Liverpool Rd. and 61s Project:

Hobart, IN

Hobart, IN

GPS Northing:

0.0 0.0

Location: Drain Area:

Southwest

GPS Easting:

Cover Shape:

Circular

GPS Accuracy: Evidence of Surcharge: **Nearest Meter**

Cover Size:

22.5

Potential for Runoff:

Yes None

Comments:

O&M Index:

0.00

2.00 O&M Quick:

2100 0000 2100

O&M Rating: Structural Rating:

2.00 0.00 2.00

Structural Index: Overall Index:

Structural Quick: 2.00 Overall Quick:

Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
-209-025				
.0	MGP	General Photo	10	NA
2.2	MGP	General Photo	28	NA
9.6	DAZ	Deposits Attached Other	57	M 2
11.4	MGO	General Observation	71	NA



Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

2 Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 9.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 11.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock Start/From Clock To:

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3