Manhole Inspection Report



Date: 03/24/2018 Weather: Coding: RZMACP

 MH#:
 M-209-026
 Owner:
 NA
 Len. Surveyed:
 7.2

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.4

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: South of 62nd Pl. 96' East of Liverpo Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-209-026				
.0	MGP	General Photo	10	NA
2.4	MGP	General Photo	29	NA
2.6	IS	Infil Stain	43	NA
4.5	DAZ	Deposits Attached Other	59	M 2
6.2	MGO	General Observation	74	NA
Camera Direction				

Code:



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 2.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12
Clock To: 4
1st Value:
2nd Value:

Value Percent: Step: **NO**

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 4.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 10.000
Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 6.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023