Manhole Inspection Report



Date: **04/13/2018** Weather:

 MH#:
 M-303-045.2
 Owner:
 NA
 Len. Surveyed:
 6.5

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 7.6

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

RZMACP

Coding:

Street: 96' North of 39th Ave. at Brown St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Northwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	1.33	O&M Quick:	2112	O&M Rating:	4.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	1.33	Overall Quick:	2112	Overall Rating:	4.00

Wednesday, May 3, 2023

Posit	tion Code	Observation	Video (sec)	Grade
M-303-045.2				
0.	MGO	General Observation	10	NA
0.	RFJ	Roots Fine Joint	21	M 1
4.0	RFJ	Roots Fine Joint	41	M 1
6.5	DSGV	Deposits Settled Gravel	58	M 2
Camera Direction				



Description:

Clock Start/From:
Clock To:
1st Value:
2nd Value:

General Observation

General Observation

General Observation

0

0

1st Value:
2nd Value:

MGO

Step: NO
Remarks: access MH

Value Percent:

Wednesday, May 3, 2023 2

Code:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): .0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 4.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 12
Clock To:
1st Value:

Step: NO

Remarks:

2nd Value: Value Percent:



Code: **DSGV**

Description: Deposits Settled Gravel

Distance (ft): 6.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks:

Wednesday, May 3, 2023 3