Manhole Inspection Report



Date: **04/13/2018** Weather:

MH#: M-303-063 Owner: NA Len. Surveyed: 5.0
P.O.#: Surveyor: Jen Costello Rim to Invert: 6.3

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

RZMACP

Coding:

Street: S. Hanson Blvd. 171' West of E. Hans Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Northwest GPS Accuracy: Nearest Meter


Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	1.50	Structural Quick:	2111	Structural Rating:	3.00
Overall Index:	1.50	Overall Quick:	2111	Overall Rating:	3.00

Wednesday, May 3, 2023

	Code	Observation	Video (sec)	Grade
803-063				
.0	MGO	General Observation	10	NA
.7	CL	Crack Longitudinal	23	S 2
7.7	SRI	Surface Roughness Increased	35	S 1
1.1	MGP	General Photo	49	NA
5.0	MGO	General Observation	69	NA




Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: CL

Description: Crack Longitudinal

Distance (ft): .7
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: SRI

Description: Surface Roughness Increased

Distance (ft): .7
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: MGP

Description: General Photo

Distance (ft): 1.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 5.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY