Manhole Inspection Report



Date: 04/13/2018 Weather: Coding: RZMACP

 MH#:
 M-303-067
 Owner:
 NA
 Len. Surveyed:
 3.6

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 5.0

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: N. Hansen Blvd. and E. Hanson Blvd. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Northwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	1.00	O&M Quick:	1100	O&M Rating:	1.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	1.00	Overall Ouick:	1100	Overall Rating:	1.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
-803-067				
.0	MGO	General Observation	10	NA
0.	RFJ	Roots Fine Joint	21	M 1
1.5	MGP	General Photo	37	NA
3.6	MGO	General Observation	54	NA



Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

MGO

General Observation

Value Percent:

Code:

Description:

Step: NO

Remarks: ACCESS MH



Code: RFJ

Description: Roots Fine Joint

Distance (ft): .0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 3.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME

Wednesday, May 3, 2023