## **Manhole Inspection Report**



Date: **04/12/2018** Weather:

MH#: M-303-071 Owner: NA Len. Surveyed: 4.4
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 5.1

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

**RZMACP** 

Coding:

Hobart, IN

Street: Ridgelawn Dr. and 39th Ave. To the Project:
City: Hobart, IN GPS Northing:

 Hobart, IN
 GPS Northing:
 2895418.342

 GPS Easting:
 2895418.342

Location: GPS Easting: **2895418.34**2

Drain Area: **Northwest** GPS Accuracy: **Sub-Meter** 


Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2200	Overall Rating:	4.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
03-071				
.0	MGP	General Photo	10	NA
1.4	IS	Infil Stain	24	NA
1.9	MGP	General Photo	39	NA
2.4	IS	Infil Stain	54	NA
3.0	OBZ	Obstacle Other	67	M 2
3.4	DAZ	Deposits Attached Other	79	M 2
3.9	MGO	General Observation	91	NA



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: IS


Description: Infil Stain

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11
Clock To: 3
1st Value:
2nd Value:

Value Percent:

Step: NO

Remarks:



Code: MGP


Description: General Photo

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: IS

Description: Infil Stain

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:


Value Percent:

Step:

NO

Wednesday, May 3, 2023

Remarks:



Code: OBZ

Description: Obstacle Other

Distance (ft): 3.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000
Step: NO
Remarks: Wood



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 3.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 3.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.