

Manhole Inspection Report




Date:	04/12/2018	Weather:		Coding:	RZMACP
MH#:	M-303-072	Owner:	NA	Len. Surveyed:	2.7
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	3.4
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)

Street:	Ridgelawn St. 369' North of Old Ridg	Project:	Hobart, IN
City:	Hobart, IN	GPS Northing:	2895423.225
Location:		GPS Easting:	2895423.225
Drain Area:	Northwest	GPS Accuracy:	Sub-Meter
Cover Shape:	Circular	Evidence of Surcharge:	No
Cover Size:	23.0	Potential for Runoff:	None
Comments:			

O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00

Position	Code	Observation	Video (sec)	Grade
.0	MGP	General Photo	10	NA
1.0	MGP	General Photo	26	NA
1.9	DAZ	Deposits Attached Other	41	M 3
2.3	MGO	General Observation	53	NA

Code:	MGP
Description:	General Photo



Code: **MGP**
Description: **General Photo**

Distance (ft): **1.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:



Code: **DAZ**
Description: **Deposits Attached Other**

Distance (ft): **1.9**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent: **15.000**
Step: **NO**
Remarks: **Mixed materials**



Code: **MGO**
Description: **General Observation**

Distance (ft): **2.3**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **Ins. Comp.**