Manhole Inspection Report



Date:

Customer:

04/12/2018

Weather:

Cert. #:

Coding:

RZMACP

MH#:

M-304-001

Owner: NA

Len. Surveyed: 6.8 8.0

P.O.#:

John Kuglmaier Surveyor:

Rim to Invert:

Concrete Wall Material:

(reinforced)

Street:

Ridge Rd. 662' East of W. Hansen Blv Project:

Hobart, IN

City:

Hobart, IN

GPS Northing: 2896733.786

Location:

GPS Easting:

2896733.786

Drain Area:

Northwest

GPS Accuracy:

U-1215-07002349

Sub-Meter

Cover Shape:

Circular

Evidence of Surcharge:

Yes

Cover Size:

23.0

Potential for Runoff: None

Comments:

O&M Index:

2.00 0.00

O&M Quick:

2100 0000

2100

O&M Rating: Structural Rating:

2.00 0.00

2.00

Structural Index: Overall Index:

Structural Quick: 2.00 Overall Quick:


Overall Rating:

Wednesday, May 3, 2023

1

P	osition Code	e Observation	Video (sec)	Grade
M-804-001				
.0	MGP	General Photo	10	NA
1.	9 MGP	General Photo	28	NA
4.	7 DSF	Deposits Settled Fine	47	M 2
6.	0 MGC	General Observation	61	NA
Camera Direction				
oirec				
ora				
a a				
•				
- 111				
- 111				
- 111				
- 11				
- 11				
	1			
	I			

Code:



Description:	General Photo
Distance (ft): Structural Grade: O&M Grade:	.0 0 0
Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	
Step: Remarks:	NO

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 4.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: MGO

Description: General Observation



Distance (ft): **6.0** Structural Grade: **0**

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3