Manhole Inspection Report



04/20/2018 Date: Weather:

M-305-029 Owner:

MH#: NA Len. Surveyed: 9.5 P.O.#: Surveyor: Jen Costello Rim to Invert: 11.0 Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

RZMACP

Coding:

Wild Rose Dr. 142' North of Crows N Project: Hobart, IN Street:

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: 0.0

Drain Area: West **GPS Accuracy: Nearest Meter**

Cover Shape: Circular Evidence of Surcharge: No 23.0 Potential for Runoff: Cover Size: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	3.00	Structural Quick:	3100	Structural Rating:	3.00
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00

1 Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-\$05-02	29				
	0. //	MGO	General Observation	11	NA
- 11	\0	CM	Crack Multiple	22	S 3
- 11	1.3	MGO	General Observation	38	NA
	5.6	IS	Infil Stain	60	NA
- 11	9.5	MGO	General Observation	80	NA
Camera Direction					



Code: MGO Description: **General Observation**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:

NO

Remarks: **ACCESS MH**



Code: CM

Description: Crack Multiple

Distance (ft): .0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IS

Description: Infil Stain

Distance (ft): 5.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12
Clock To: 6
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 9.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023