

Manhole Inspection Report



Date:	09/27/2022	Weather:		Coding:	RZMACP
MH#:	M-305-032	Owner:	NA	Len. Surveyed:	6.1
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	6.5
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (cast in place)

Street:	North of Crows Nest Dr. 106' East of	Project:	Hobart, IN
City:	Hobart, IN	GPS Northing:	2288666.453
Location:	Yard	GPS Easting:	2894531.994
Drain Area:	West	GPS Accuracy:	Sub-Meter
Cover Shape:	Circular	Evidence of Surcharge:	No
Cover Size:	24.0	Potential for Runoff:	None
Comments:			


O&M Index:	2.50	O&M Quick:	3121	O&M Rating:	5.00
Structural Index:	1.50	Structural Quick:	3216	Structural Rating:	12.00
Overall Index:	1.70	Overall Quick:	3321	Overall Rating:	17.00

Position	Code	Observation	Video (sec)	Grade
<div> <div> <div>M-305-032</div> <div> <div>Camera Direction</div> <div></div> </div> </div> <div></div> </div>				
.0	MGO	General Observation	10	NA
.0	SRI	Surface Roughness Increased	21	S 1
2.3	IW	Infil Weeper	39	M 2
2.3	MGO	General Observation	51	NA
6.1	SAV	Surface Aggregate Visible	72	S 3
6.1	SAV	Surface Aggregate Visible	83	S 3
6.1	DSF	Deposits Settled Fine	95	M 3
6.1	SRI	Surface Roughness Increased	106	S 1
6.1	MGO	General Observation	117	NA




Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **access mh**




Code:	SRI
Description:	Surface Roughness Increased
Distance (ft):	.0
Structural Grade:	1
O&M Grade:	0
Clock Start/From:	12
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	




Code:	IW
Description:	Infil Weeper
Distance (ft):	2.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	MGO
Description:	General Observation
Distance (ft):	2.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	underside of frame



Code:	SAV
Description:	Surface Aggregate Visible
Distance (ft):	6.1
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	SAV
Description:	Surface Aggregate Visible
Distance (ft):	6.1
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	3
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	DSF
Description:	Deposits Settled Fine
Distance (ft):	6.1
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	4
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	20.000
Step:	NO
Remarks:	



Code: **SRI**
Description: **Surface Roughness Increased**

Distance (ft): **6.1**
Structural Grade: **1**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **2**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:



Code: **MGO**
Description: **General Observation**

Distance (ft): **6.1**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **end of survey**