

Manhole Inspection Report



Date:	04/28/2018	Weather:		Coding:	RZMACP
MH#:	M-305-054	Owner:	NA	Len. Surveyed:	7.0
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	8.0
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick


Street:	346' North of 3rd St. East of Woodla	Project:	Hobart, IN
City:	Hobart, IN	GPS Northing:	2896778.373
Location:		GPS Easting:	2896778.373
Drain Area:	West	GPS Accuracy:	Sub-Meter
Cover Shape:	Circular	Evidence of Surcharge:	No
Cover Size:	23.0	Potential for Runoff:	None
Comments:			

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Quick:	3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick:	3121	Overall Rating:	5.00

The diagram illustrates a vertical pole with a camera at the top. A red arrow labeled "Camera Direction" points downwards from the camera. The pole is divided into segments by horizontal lines. A table to the right of the pole provides data for five specific positions along the pole.

Position	Code	Observation	Video (sec)	Grade
.0	MGO	General Observation	11	NA
1.6	MGP	General Photo	27	NA
5.2	SAP	Surface Aggregate Projecting	48	S 3
5.2	DSZ	Deposits Settled Other	59	M 2
7.0	MGO	General Observation	75	NA

Code:	MGO
Description:	General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	MGP
Description:	General Photo
Distance (ft):	1.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code:	SAP
Description:	Surface Aggregate Projecting
Distance (ft):	5.2
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	6
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	DSZ
Description:	Deposits Settled Other
Distance (ft):	5.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	6
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	MISC



Code:	MGO
Description:	General Observation
Distance (ft):	7.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY