Manhole Inspection Report



Date:

03/23/2018

Weather:

Overall Quick:

NA

Coding:

RZMACP

18.9

19.9

MH#: P.O.#:

M-308-002

Owner:

Len. Surveyed: Rim to Invert:

Customer:

John Kuglmaier Surveyor: U-1215-07002349 Cert. #:

Wall Material:

Concrete (reinforced)

Street:

North of 61st Ave. 494' West of Clay Project:

Hobart, IN

City: Location: Hobart, IN

GPS Northing:

0.0

Drain Area:

GPS Easting:

0.0

Cover Shape:

Southwest

GPS Accuracy:

Nearest Meter

Cover Size:

Circular

22.5

Evidence of Surcharge: No

Comments:

Potential for Runoff:

None

O&M Index:				
Structural Index:				

Overall Index:


2.00	O&M Quick:
0.00	Structural Quick:
2.00	Overall Quick:

2100 O&M Rating: 0000 Structural Rating: 2100 Overall Rating:

0.00 2.00

2.00

Position	Code	Observation	Video (sec)	Grade
08-002				
.0	MGP	General Photo	10	NA
2.7	MGP	General Photo	29	NA
15.9	IS	Infil Stain	69	NA
16.4	DAZ	Deposits Attached Other	82	M 2
17.3	MGO	General Observation	95	NA



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 15.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 8

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 16.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 17.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4