## **Manhole Inspection Report**



Date:

03/23/2018

Weather:

Cert. #:

Coding:

**RZMACP** 

MH#:

M-308-008

Owner:

Len. Surveyed:

14.9

P.O.#:

NA John Kuglmaier Surveyor:

Rim to Invert:

17.7 Concrete

Customer:

U-1215-07002349

Wall Material:

(reinforced)

Street: City:

61st Ave. East of Amber Dr.

Project:

Hobart, IN

Hobart, IN

**GPS Northing:** 

0.0

Location:

GPS Easting:

0.0

Drain Area:

Southwest

GPS Accuracy:

**Nearest Meter** 

Cover Shape: Cover Size:

Circular

Evidence of Surcharge:

Yes

Comments:

22.5

Potential for Runoff:

None

O&M Index:

2.00 O&M Quick: 0.00

2200 0000 2200

O&M Rating: Structural Rating:

4.00 0.00

4.00

Structural Index: Overall Index:

Structural Quick: 2.00 Overall Quick:

Overall Rating:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
8-008				
.0	MGP	General Photo	10	NA
2.8	MGP	General Photo	30	NA
/4.9	DAGS	Deposits Attached Grease	48	M 2
//11.3	IS	Infil Stain	72	NA
12.5	DAZ	Deposits Attached Other	86	M 2
13.0	MGO	General Observation	99	NA



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 4.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 11.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 12.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 13.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.