Manhole Inspection Report



Date: 03/27/2018 Weather: Coding: RZMACP

 MH#:
 M-308-017
 Owner:
 NA
 Len. Surveyed:
 5.3

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 5.9

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Ruby Ct Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

F	Position	Code	Observation	Video (sec)	Grade
M-808-017					
	0	MGP	General Photo	10	NA
2	2.3	MGP	General Photo	28	NA
	2.7	DAZ	Deposits Attached Other	43	M 2
4	1.2	MGO	General Observation	57	NA
Camera Direction					


Code:



General Photo Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 2.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 4.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3