Manhole Inspection Report



Date: 04/10/2018 Weather: Coding: RZMACP

MH#: M-404-038 Owner: NA Len. Surveyed: 3.3
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 3.9

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Dearborn St. 111' North of Old Ridg Project: Hobart, IN

City: Hobart, IN GPS Northing: 2898747.508

Location: GPS Easting: 2898747.508

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
л-404-038				
.0	MGP	General Photo	10	NA
1.5	DAZ	Deposits Attached Other	25	M 2
1.6	MGP	General Photo	38	NA
2.8	MGO	General Observation	54	NA
Camera Direction				


Code:



Description:	General Photo		
(6)	_		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023



Code: DAZ

Description: **Deposits Attached Other**

Distance (ft): 1.5 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 12 Clock To: 12

1st Value: 2nd Value:

10.000 Value Percent: Step: NO

Remarks: **Mixed materials**





Code: MGP

Description: **General Photo**

Distance (ft): 1.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent: Step:

NO

Remarks:

Code:



MGO

Description: **General Observation**



Distance (ft): 2.8 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3