Manhole Inspection Report



Date: 05/16/2018 Weather: Coding: RZMACP

 MH#:
 M-405-052
 Owner:
 NA
 Len. Surveyed:
 6.7

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 7.2

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: 348' North of 3rd St. West of Oakwo Project: Hobart, IN

City: Hobart, IN GPS Northing: 41.53378677

Location: GPS Easting: -87.28546906

Drain Area: West GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	o Code	Observation	Video (sec)	Grade
M-405-052				
.0	MGO	General Observation	10	NA
.9	IS	Infil Stain	23	NA
1.6	MGO	General Observation	37	NA
/ 5.8	DSF	Deposits Settled Fine	58	M 2
6.7	MGO	General Observation	71	NA
Camera Direction				



General Observation Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACESS MH**

MGO

Wednesday, May 3, 2023 2

Code:



Code: IS

Description: Infil Stain

Distance (ft): .9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 5.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 6.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY