## **Manhole Inspection Report**



Date: 04/28/2018 Weather: Coding: RZMACP

 MH#:
 M-405-059
 Owner:
 NA
 Len. Surveyed:
 5.3

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 6.5

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: South of West 2nd Pl. and 165' East Project: Hobart, IN

City: Hobart, IN GPS Northing: 2897102.048

Location: GPS Easting: **2897102.048**Drain Area: **West** GPS Accuracy: **Sub-Meter** 

Cover Shape: Circular Evidence of Surcharge: No

Cover Size: 23.0 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-405-059				
.0	MGO	General Observation	10	NA
1.1	MGO	General Observation	26	NA
4.1	DSGV	Deposits Settled Gravel	45	M 2
5.3	MGO	General Observation	58	NA
Camera Direction				



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 1.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSGV** 

Description: Deposits Settled Gravel

Distance (ft): 4.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Value Percent: 5.000 Step: NO

Remarks:

Code:

Description: General Observation

MGO



Distance (ft): 5.3
Structural Grade: 0

O&M Grade: **0** 

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023