Manhole Inspection Report



Date: 09/25/2022 Weather: Coding: RZMACP

 MH#:
 M-407-003
 Owner:
 NA
 Len. Surveyed:
 2.7

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 3.7

Customer: Cert. #: U-907-5518 Wall Material: Concrete (cast in

Hobart, IN

Project:

place)

Street: On Lake View Dr. South of 10th St.

City:Hobart, INGPS Northing:2284505.156Location:Local Rural StreetsGPS Easting:2898628.603Drain Area:SouthwestGPS Accuracy:Sub-Meter

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: 24.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00	
Structural Index:	1.00	Structural Quick:	1100	Structural Rating:	1.00	
Overall Index:	1.67	Overall Ouick:	2211	Overall Rating:	5.00	

Position	Code	Observation	Video (sec)	Grade
7-003				
.0	MGO	General Observation	10	NA
0.	SRI	Surface Roughness Increased	21	S 1
2.7	DSF	Deposits Settled Fine	38	M 2
2.7	DSF	Deposits Settled Fine	49	M 2
2.7	MGO	General Observation	61	NA

Code:

Description:



·	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	access mh

MGO

General Observation



Code: SRI

Description: Surface Roughness Increased

Distance (ft): .0
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 2.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: DSF

Description: Deposits Settled Fine



Distance (ft): 2.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 5

Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end of survey