Manhole Inspection Report



Date: 03/27/2018 Weather: Coding: RZMACP

 MH#:
 M-4074-011
 Owner:
 NA
 Len. Surveyed:
 5.6

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 6.7

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: On Lake Side Dr. South of 10th St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-4074-011					
	.0	MGP	General Photo	10	NA
	2.0	MGP	General Photo	28	NA
	3.1	DSF	Deposits Settled Fine	44	M 2
	4.5	MGO	General Observation	58	NA
Camera Direction					


Code:



Description:	General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From:	.0 0 0
Clock To: 1st Value: 2nd Value: Value Percent:	
Step: Remarks:	NO

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To: 12

1st Value: 2nd Value: Value Percent:

ent: **10.000 NO**

Remarks:

Step:

Code:

Description: General Observation

MGO



Distance (ft): 4.5
Structural Grade: 0

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO
Remarks: Ins. Comp.

Wednesday, May 3, 2023 3