Manhole Inspection Report



 Date:
 04/09/2018
 Weather:
 Coding:
 RZMACP

 MH#:
 M-503-004
 Owner:
 NA
 Len. Surveyed:
 12.8

P.O.#: Surveyor: John Kuglmaier Rim to Invert: 14.5
Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 163' West of Wisconsin St. 243' Sout Project: Hobart, IN

City: Hobart, IN GPS Northing: 2901618.819

Location: GPS Easting: 2901618.819

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: Yes

Cover Size: 23.0 Potential for Runoff: None

Comments:

2.00 3111 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 3111 4.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Code	Observation	Video (sec)	Grade
603-004				
.0	MGP	General Photo	10	NA
2.3	MGP	General Photo	28	NA
9.1	RFJ	Roots Fine Joint	56	M 1
10.1	DAZ	Deposits Attached Other	69	M 3
11.6	MGO	General Observation	83	NA



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP


Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 9.1
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 10.1
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 15.000 Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 11.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023