Manhole Inspection Report



Date:

04/09/2018

Weather:

Coding:

RZMACP

5.6

MH#:

M-503-024

Owner: NA Len. Surveyed: 3.9

P.O.#:

Surveyor: John Kuglmaier

Rim to Invert:

Customer:

U-1215-07002349 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

166' South of 39th Ave. 529' West of Project:

Hobart, IN 2900512.665

Location:

Hobart, IN

GPS Northing:

Drain Area:

GPS Easting:

2900512.665

Cover Shape:

Northwest

GPS Accuracy:

Sub-Meter

Cover Size:

Circular

23.0

Evidence of Surcharge: No

Comments:

Potential for Runoff:

None

O&M Index:
Structural Index:

Overall Index:

2.00	
0.00	
2.00	

O&M Quick: Structural Quick:

Overall Quick:

2200 0000 2200

O&M Rating: Structural Rating: Overall Rating:

4.00 0.00 4.00

	Code	Observation	Video (sec)	Grade
-503-024				
.0	MGP	General Photo	10	NA
2.2	MGP	General Photo	28	NA
2.3	OBZ	Obstacle Other	42	M 2
3.0	DSF	Deposits Settled Fine	54	M 2
3.5	MGO	General Observation	67	NA



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: **MGP**

Description: **General Photo**

Distance (ft): 2.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: OBZ

Description: **Obstacle Other**

Distance (ft): 2.3 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 4 Clock To: 10 1st Value:

2nd Value: Value Percent:

10.000 NO

Step: Remarks: Pole



Code: DSF

Deposits Settled Fine Description:

Distance (ft): 3.0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 12 Clock To: 12 1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks:

3 Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 3.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023