Manhole Inspection Report



Date: 04/09/2018 Weather: Coding: RZMACP

MH#: M-503-027.5 Owner: NA Len. Surveyed: 6.0 P.O.#: Surveyor: John Kuglmaier Rim to Invert: 7.0

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Virginia St. 219' North of 42nd Ave. Project: Hobart, IN

 City:
 Hobart, IN
 GPS Northing:
 2900997.074

 Location:
 GPS Easting:
 2900997.074

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None


Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
И-5 <mark>03-02</mark> 7.5				
.0	MGP	General Photo	10	NA
2.6	MGP	General Photo	29	NA
4.0	DAZ	Deposits Attached Other	45	M 2
5.3	MGO	General Observation	59	NA
Camera Direction				

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 4.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 5.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/Pro Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3