Date:	04/09/2018	Weather:		Coding:	RZMACP
MH#:	M-503-048	Owner:	NA	Len. Surveyed:	6.2
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	7.7
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	45' West of Virgini	a St. 179' South of	Project:	Hobart, IN	
City:	Hobart, IN	(GPS Northing:	2900990.995	
Location:		(GPS Easting:	2900990.995	
Drain Area:	Northwest	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	E	Evidence of Surcharge:	No	
Cover Size: Comments:	23.0	ſ	Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00
Structural Index:	0.00	Structural Quid	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2200	Overall Rating:	4.00

	Position	Code	Observation	Video (sec)	Grade
M-503-0	48				
\mathbf{i}	0. 🗸	MGP	General Photo	10	NA
	2.0	MGP	General Photo	28	NA
	4.1	DAZ	Deposits Attached Other	46	M 2
	4.7	OBZ	Obstacle Other	58	M 2
- 11	4.7	IS	Infil Stain	70	NA
- 11	5.6	MGO	General Observation	84	NA
Camera Direction					



Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:MGPDescription:General PhotoDistance (ft):2.0Structural Grade:0O&M Grade:0Clock Start/From:Clock To:

1st Value: 2nd Value: Value Percent:

Step:

Remarks:

Code: Descri Distan Structu O&M C Clock S

Description:	Deposits Attached Other
Distance (ft):	4.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	Mixed materials

NO

DAZ



OBZ
Obstacle Other
4.7
0
2
4
5.000
YES
Unknown



Code:	IS
Description:	Infil Stain
Distance (ft):	4.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	MGO
Description:	General Observation
Distance (ft):	5.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.