## **Manhole Inspection Report**



Date: 05/13/2018 Weather: Coding: RZMACP

 MH#:
 M-504-020
 Owner:
 NA
 Len. Surveyed:
 9.9

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 11.0

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: Wisconsin St. 165' South of Old Ridg Project: Hobart, IN

City: Hobart, IN GPS Northing: 2901798.406

Location: GPS Easting: 2901798.406
Drain Area: West GPS Accuracy: Sub-Meter


Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	3.00	Structural Quick:	3100	Structural Rating:	3.00
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
604-020				
.3	MGP	General Photo	11	NA
2.2	MGO	General Observation	25	NA
2.2	SAV	Surface Aggregate Visible	36	S 3
10.5	MGO	General Observation	63	NA



Description:	General Photo		
Distance (ft):	.3		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:	access mh		

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGO

Description: General Observation

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: broken step



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 2.2
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: MGO

Description: General Observation

Distance (ft): 10.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey

Wednesday, May 3, 2023