
Date:	05/13/2018	Weather:		Coding:	RZMACP
MH#:	M-504-033	Owner:	NA	Len. Surveyed:	11.0
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	12.3
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	44th Ave. 168' We	st of Delaware St.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	41.53821182	
Location:			GPS Easting:	-87.27362061	
Drain Area:	West		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qui	ck: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick	: 3121	Overall Rating:	5.00

Posi	tion Code	Observation	Video (sec)	Grade
1-504-033				
0.	MGO	General Observation	10	NA
.2	DB	Displaced Brick	22	S 3
7.3	MGO	General Observation	48	NA
11.0	OBR	Obstacle Rocks	67	M 2
11.0	MGO	General Observation	78	NA
Camera Direction				



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	DB
Description:	Displaced Brick
Distance (ft):	.2
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	3
Clock To:	6
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Distance (ft):7.3Structural Grade:0O&M Grade:0Clock Start/From:0Clock To:1st Value:1st Value:2nd Value:Value Percent:Step:Step:NORemarks:MISSING AND BROKEN STEPS	



Code: Description:	OBR Obstacle Rocks
Distance (ft):	11.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	6
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code: Description:

MGO General Observation

Distance (ft):	11.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY